TO: Patrick Nejand, Project Manager

Ken Mass, Project Manager

United States Army Corps of Engineers (USACE)

FROM: Nathan Canaris, Project Manager

Los Alamos Technical Associates, Inc. (LATA)

SUBJECT: June 2015 Inspection Report for the former Cornell Dubilier Electronics (CDE) Superfund

Site, South Plainfield, New Jersey

LATA Project # 11266

Contract # W912DQ-09-D-3003,

Task Order # 0011

DATE: June 30, 2015

CURRENT ACTIVITIES

LATA's technician visited the Cornell Dubilier Electronics (CDE) Superfund Site for the regularly scheduled inspection visit on June 10, 2015 to perform the routine inspection of the facilities.

Work performed during the visit included; picked up trash from the fence line, inspected the catch basin and drainage basin system, inspected the perimeter fence, gates, etc., pulled woody vegetation from accessible areas of the drainage basin, downloaded the data from the basin dataloggers and performed a walking inspection of the asphalt cap areas. Copies of the inspection forms and photo documentation of the site visit are attached to this report.

One bag of trash (paper, plastic bottles, etc.) were picked up from around the fence line in various areas. The trash was disposed of in the local technician's office dumpster.

Attached with this report are preliminary drain time analyses for the surface sand filter using data from the barometrically compensated Solinst® level logger which was installed in the detention basin in September 2014. The precipitation data is provided by the USGS from a heated rain gauge located approximately five miles from the site in Middlesex, NJ.

MANPOWER REPORTING

Date	LATA Labor
June 10, 2015	Approx. 2.5 hrs.

OUTSTANDING ISSUES/RESOLUTIONS

None

PLANS FOR NEXT MONTH

Plans for the June 2015 visit includes inspection and general housekeeping activities and downloading the drainage basin level datalogger.

Site Inspection Forms and Photo Log

Inspection being Co	nducted		X	Monthly					
Quarterly		Annually			_After 1" or Gre	eater Rai	nfall _		
Inspection Date:	6/10/2015			<u> </u>	Weather		Sunny, 70s		
Inspectors Name	Sunil Samaro	00							
Basin Inspection:							.,		21/2
Catch Basins (23 Str	ucturos)						Yes	No	N/A
1. Are catch basins p	-	g?					X		
2. Are the catch basi		_	t and debris	;?			X	\equiv	=
3. Has vegetation be								\equiv	
_									
4. Are there any sign If yes, which catch be	_	deteriorat	ion of catch	i basins?				X	
(Refer to Record Dra	• •	basin num	nbers)						
Chamana Bahandi	an Darin and C		d File						
Stormwater Detenti	on Basin and S	urtace San	a Filter:						
5. Does the basin ha	ve pooled or sta	anding wat	er?				Х		
If yes, describe wher	•	Ü		s observed i	n all 3 detention	n basins			
6. What is the water	height	4 to 6	inches						
Approximately how	•	s the last ra	ainfall?						
How many inches of									
7. Does the bottom a	appear relativel	y flat? No s	sand has wa	ished away?			X		
8. Are concentrated	flows of runoff	being unex	spectedly di	rected into	the basin?			X	
If yes, describe wher	re	_							
9. Is there any dama	ge to the sand I	oed or berr	ms?					X	
10. Has vegetation b	een removed fr	om the ba	sin areas?						X
Woody vegetation v	vas removed by	pulling/c	utting at gr	ound level a	round the top of	f the det	ention basi	ns.	

Inlet and Outlet Structures: 11. Are the five inlet and outlet structures draining properly?	X		
12. Is there any standing water? If yes, describe where		X	
13. Are the inlets clear of trash, sediment and debris?	Χ		
14. Are the outlets (standpipes, 3" Orifice, secondary outlet and emergency spillway) clear of trash, sediment, and debris?	X		
15. are there any signs of damage or deterioration of inlet/outlet structures? If yes, describe where		X	
16. Has vegetation been removed from inlet and outlets?			Χ
Additional descriptions of where repairs or maintenance is needed:			
Subcontractors are on-site performing repairs to damaged areas in the asphalt.			
Inspector's Signature Secril Surnardo			

Inspection Date:	6/10/2015	Weather	Sunny, 70s		
Inspectors Name	Sunil Samaroo				_
		"Tree Grove" Inspection			
			Yes	No	N/A
1. Is there any tree da	mage from storms?			X	
If yes, describe: 2. Is there an accumulation of the second of the seco	ation of two odobnica				
If yes, describe:	ation of tree debris?			X	
3. Do any trees appea	r infested?				X
If yes, describe:					
4. Do any trees appea	r malnourished?				X
If yes, describe:					
	erly Seasonal Maintenan	ce Performed?			Χ
Date of previous main		integrand Manual)			
•	of the Operation & Mai I Arborist Inspection per	·			
Date of previous inspe	·				
	of the Operation & Mai	intenance Manual)			
Additional description	s of where repairs or ma	aintenance is needed:			
Tree buffe	r being maintained "as	is" by direction of USACE and EPA.			
	_				
Inspector's Signature	Suril x	Lumario			

Inspection Date:	6/10/2015	Weather	Sunny, 70s	
Inspectors Name	Sunil Samaroo			
Debris, Trash, Vege Comments	tation and Sediment Removal and	Inspections		
	d trash from perimeter fence.			
	of trash disposed of at URS dumps	ster.		
	the site remains in good condition			
General Housekeep	ing			
Comments				
	has minor cracking predominantly			
Subcont	ractors are on-site performing repa	airs to damaged areas in the asp	onait.	
Fencing and Gates				
Comments				
GOOD				
Trash and Debris				
Comments				
(See abo	ove)			
Snow Removal				
Comments				
N/A				
· · · · · · · · · · · · · · · · · · ·				

Pavement Inspection (Part of Annual Inspection)

Inspector's Signature

	Yes	No	N/A
Is there any standing water? If yes, describe where			X
2. Are there any signs of cracking?			
If so, note location and maintenance effort below.			
3. Are there any signs of disintegration?			X
If so, note location and maintenance effort below.			
4. Are there any sins of distortion?			X
If so, note location and maintenance effort below.			
5. Has all vegetation been removed?	Χ		
If applicable, note location of vegetation below			
6. Has usage of the site increase to a point that warrants a Pavement Condition			Χ
Index (PCI) Survey?			
7. Have any Critical Preventative Maintenance (CPM) Pavement Treatments			X
been applied? When was date of the last CPM treatment?			
(Refer to Section 2.2.3 of the Operations & Maintenance Manual)			
Additional descriptions of where repairs or maintenance is needed:			
Cracks in asphalt developing in the area of the water tower, previously observe	d.		
Subcontractors are on-site performing repairs to damaged areas in the asphalt.			
	-	-	-
Inspector's Signature			

(completed twice a yea	r after a design rainfall event)
Date:	
Design Rainfall Event In Requirements: 1.25" of	
Start: Stop:	
Inches of Rainfall:	

Inspection Data

Basin Drainage Rate Inspection:

Start inspections 16 hours after design rain event Perform subsequent inspection every 2 hours until height of water drops below the to of the aggregate in the middle basin

Inspection Run #	Target time from Event (hrs)	Actual Time	Water Height (ft)
1	16		
2	18		
3	20		
4	22		
5	24		
6	26		
7	28		
8	30		
9	32		
10	34		

Note approximate time water was drained below top of sand bed and compared to the normal drain time of 21 hrs.

Inspector's Signature

06-10-2015 Cornell-Dubilier Electronics

Site Inspection photos

Fence drive by inspection photos







Additional site photos

















Preliminary Surface Sand Filter Drain Time Analysis




Figure 1. Timeseries of water level above the sand filter versus precipitation.

The full timeseries of water level above the sand filter versus precipitation measured at the rain gauge in Middlesex, NJ is presented in Figure 1. Individual precipitation events and their associated drainage times are presented below.




Figure 2. Sand filter drainage time for 31 May 2015 Storm Event.

During the period 31 May 2015 – 2 June 2015, the site received the largest amount of precipitation recorded since the pressure transducer was installed in the detention basin in September 2014. Figure 2 shows the water level above the sand filter along with precipitation data from the rain gauge in Middlesex, NJ. Twenty-four hour precipitation totals are listed below in Table 1.

Table 1. Twenty-four hour precipitation totals, 31 May 2015 – 2 June 2015

Date	Total Precipitation [in]
5/31/15	0.36
6/1/15	1.08
6/2/15	0.67

During this period, the highest rain rate recorded was 0.78 inches in a two hour period on 1 June. This is below the design storm event of 1.25 inches in a two hour period.




Figure 3. Sand filter drainage time for 31 May 2015 Storm Event with linear regressions during drainage.

Figure 3 includes three linear regressions fitted to the water level above the sand filter between precipitation events while the sand filter is draining. These regressions show that the sand filter has an average drain rate of approximately 0.5 ft/day.




Figure 3. Sand filter drainage time for 15 October 2014 Storm Event with linear regression during drainage.

Figure 3 includes a linear regressions fitted to the water level above the sand filter after precipitation on 15-16 October while the sand filter is draining. This regression shows that the sand filter has an average drain rate of slightly less than 0.5 ft/day.

From the New Jersey Stormwater Best Management Practices Manual, Equation 9.9-1:

$$A_S = \frac{(V_{QS})(TH_S)}{[(k)(\frac{D_{ST}}{2} + TH_S)(T_D)]}$$

Equation 9.9-1

Where:

As = Minimum Sand Bed Surface Area (in square feet)

Vos = Runoff Volume from the Stormwater Quality Design Storm (in cubic feet)

TH_S = Thickness of Sand in Sand Bed (in feet)

k = Sand Bed Design Permeability (in feet per day)

D_{ST} = Maximum Temporary Sand Bed Depth (in feet)

 $T_D = Sand Bed Drain Time (in days)$

Solving for the Sand Bed Drain Time (TD) and using the values and/or actual measurements below,

As = Minimum Sand Bed Surface Area = 9,660 ft²

V_{QS} = Runoff Volume from the Stormwater Quality Design Storm = 82,621 ft³

TH_S = Thickness of Sand in Sand Bed = 2 ft

k = Sand Bed Design Permeability = 4 ft/day

 D_{ST} = Maximum Temporary Sand Bed Depth = 3.5 ft

 $T_D = .88$ days or 21.1 hours

Equation 9.9-1 (Operation & Maintenance Plan, Cornell-Dubilier Electronics Superfund Site, Operable Unit 2, Appendix A) presents the design parameters for the sand bed from which it is calculated that runoff from the design storm event should drain in 21.1 hours.

Using data from the 31 May -2 June precipitation event (Figures 1 and 2) the peak water level above the sand bed for this precipitation event was 3.07 feet at 2300 hours on 2 June 2015. Using the minimum sand bed surface area (A_s) from Equation 9.9-1, and multiplying by 3.07 feet this equates to approximately 29,656 ft³ of water. Solving for T_D yields a sand bed drain time of 9.8 hours.

As shown in Figure 2, the sand bed had only drained down to a water level of 1.89 feet (net change of 1.18 feet) before the next precipitation event started at 0615 on 5 June 2015, with an average drainage rate of 0.5 feet per day.

This data suggests that the current permeability of the sand bed is significantly less than the design permeability of 4 ft/day.